




USB Update for Simplex Temperature Controllers

The USB chip on older Simplex Temperature controllers needs to be updated to work with Windows 10 drivers. To do so requires this program to be able to talk to the controller so this procedure needs to be done on an older system where the XP drivers are installed and still run.



Open the zip file by clicking on it. The program does not need to be extracted from the Zip file to run but can be if desired.

With the temperature controller connected to the USB of the PC (it does not need to be powered or turned on but can be)

Run the UsbupdateTC program




When this window appears, press the **Look for Device** button.





If the controller is located a message will be displayed. The type of controller found will change with the controllers for different devices.

If no controller is located, check that the controller USB cable is connected on each end and then push the **Look for Device** button again. If this error continues, use the old software disks to reinstall the older drivers.

Reminder: This needs to be done on an old version of windows so the older drivers can be installed.



If a controller has been found, the Upgrade button will be enabled and should be clicked.



The program will check the controller and display one of the messages above. Click the OK button.




An old configuration controller has been successfully upgraded.

You can now use the controller on old and new systems with current USB drivers. The older computer will need to have new drivers installed to continue operating.

NOTE:

Older Temperature control programs can be installed used and used on Windows 10 systems, but there is a slight incompatibility with the newer USB drivers. The following error message will be displayed when the program is started.



It is only a warning as the Data Characteristics are set correctly and the programs will operate as intended. This is eliminated with newer versions of the Temperature Control programs.

For further assistance or to upgrade Temperature Controller Software contact Simplex Scientific:

Simplex Scientific LLC
1910 Mayflower Dr
Middleton, WI 53562
Phone 608-831-4476

WWW.SIMPLEXSCI.COM

Service@simplexsci.com